

List of measurement ranges

Measurement range *	INFRA.SENS® NDIR								ULTRA.SENS® NDUV				UVRAS		
	CO ₂	CO	N ₂ O	CH ₄	C _n H _m	CF ₄	SF ₆	H ₂ O	O ₃	CL ₂	H ₂ S	SO ₂	NO ₂	NO	
100 Vol.-%	✓	✓	✓	✓	✓	✓	✓	Measurement ranges on request							
50 Vol.-%	✓	✓	✓	✓	✓		✓								
30 Vol.-%		✓	✓	✓	✓		✓			✓					
20 Vol.-%	✓														
10 Vol.-%	✓	✓		✓	✓					✓		✓			
5 Vol.-%	✓	✓		✓	✓					✓		✓			
1 Vol.-%	✓	✓		✓	✓					✓	✓	✓			
5.000 ppm	✓	✓		✓	✓		✓			✓	✓	✓	✓	✓	✓
2.000 ppm	✓	✓	✓	✓	✓				✓	✓	✓	✓	✓	✓	✓
1.000 ppm	✓	✓	✓	✓	✓		✓		✓	✓	✓	✓	✓	✓	✓
500 ppm	✓	✓	✓						✓	✓	✓	✓	✓	✓	✓
300 ppm			✓									✓	✓	✓	✓
100 ppm	✓		✓				✓		✓	✓	✓	✓	✓	✓	
50 ppm	✓						✓		✓	✓		✓	✓	✓	
10 ppm									✓	✓		✓	✓		
1 ppm									✓	✓					

* Full scale value (F.S.)